



A1 (FTH-1x10.B-Optimus911RR-ПДУ/С)

DO	N,7	22,24	N,5	3,4	1,2	
DI	33,34		29,30		35,36	
AO		23,24		25,26		54,56
AI	52,53	48,49			46,47	50,51
RS-485						55,57
Питание	U N Pe		U N Pe		U N Pe	

